


SPARK DETECTION FOR ABORT ON RETURN AIR DUCT

SEE NFPA 664 8.2.2.7.4.2 (2017 EDITION)



 **FLAMEX[®] INC.**

4365 Federal Dr.
Greensboro, NC 27407
PH (336) 299-2933 FAX (336) 299-2944